

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work
Informational Photos**



Image 1: Front of storage barn

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work
Informational Photos**



Image 2: North-west facing front corner

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 3: West side of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 4: West side of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 5: Eaves of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam**

**Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 6: South facing side of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 7: Back of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 8: Eastern-facing side of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Figure 9: Front northeast facing corner of building

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam**

**Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 10: Holes in siding

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 11: Garage Door

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts
Statement of Work**

Informational Photos



Image 12: New door

**Repair and Repainting of Littleville Storage Barn
U.S. ARMY CORPS OF ENGINEERS
Littleville Dam
Huntington, Massachusetts**

Statement of Work

Informational Photos



Image 13: Front of barn, looking up at hayloft opening.